









## Mounting instruction

AIRCELL®5

N-Connector, screwable / Art. No. 7700

 <p><b>1.</b> Cut off cable tail right-angled.</p>	 <p><b>5.</b> Cut the copper braid with a side cutter. Slit slightly a length of 6 mm of the copper foil and remove it, then remove 5 mm of the dielectric.</p>
 <p><b>2.</b> Move the nut, clamping ring and rubber washer over the cable head.</p>	 <p><b>6.</b> Move the rubber washer upfront to the contact jacket, so the rest of the copper braid is clamped between the rubber washer and the contact jacket.</p>
 <p><b>3.</b> Remove 8 mm of the outer sheathing with a knife.</p>	 <p><b>7.</b> Attach the inner pin to the tip and solder through the hole. There should be a space of 1 mm between the inner pin and the copper foil.</p>
 <p><b>4.</b> Bend copper braid upwards right-angled.</p>	 <p><b>8.</b> Insert the prepared cable end into the connector housing as far as it will go (Click). Take two open-end wrenches 11 mm to tighten the clamping nut hand-tight.</p>